COPY 601 6

25 January 1961

MERCHANDUM FOR : Chief, Mevelopment Branch, DFD-DD/P

SUBJECT

: Storage and Handling - PWA 523 Purl

REPERENCE.

: (a) OKC-0824 dated 19 August 1960 titled "Storage and Handling - PWA 523 Puel for JT11D-20A Engine"

i. As outlined in reference (a) memo, thermal stability of subject fuel is adversely affected by any contact with copper and/or eilver. Recent tests indicate that a contamination level of .05 to .10 part copper in one million parts fuel definitely deteriorates thermal stability.

- 2. Current refinery procedure calls for flushing each railroad tank car with PGA 523 fael prior to shipment. This is to eliminate any residual fuel, water, rust, scale, suspended iron particles, or fungue, as well as copper and silver.
- 3. Current Pratt & Whitney practice is to flush storage tanks and tank farm plushing with PWA 523 fuel approximately every nine months for the above reasons.
- 4. It is recommended that the procedures outlined in paragraphs 2 and 3 be followed in the handling of Project PWA 523 fuel.

| 25% 149A | SIGNED. |
|-----------------|--------------------|
| | Devslopment Branch |

Distribution: 1-C/DB/DPD

2-C/TAS/DPD 3-C/MB/DPD

445-DF0/DB

6-0PD/NI

DPD/DB/RCD sitem

20 2012